


Build better with genuine Universal Instruments performance and reliability enhancements



Upgrade/Retrofit	Description	Prerequisites/Notes
Windows 7 to Windows 10 Upgrade	Enjoy improved security and usability features.	Requires IMUPS 7.0.2 or newer. Upgrades to latest version of IMUPS 9.X with Windows 10.
Small-Footprint Clinch	Upgrade to the next-generation radial clinch to improve your machine performance.	Requires Grounding Kit if not M-Block Radial machine
Rotary Table Drive Assembly Retrofit Kit	Improve reliability and maximize drive motor and rotary disc performance. Redesigned with improved lubrication to minimize wear and rotary table drive noise.	Requires IMUPS 9.4.8 or newer
Radial Cardboard Detector	Prevent tooling damage by detecting excess cardboard at the cutter station and stopping production until it is removed or cleared.	Requires IMUPS 9.1.0 or newer
Precision Insert Pusher	Optimize part positioning and improve insertion accuracy with superior tooling design. Excellent for high-density or LED applications.	Older machine configurations may require a new Guide Jaw and Clamps to improve the Clamp opening timing

www.uic.com | email: universal@uic.com

MC-6948A

©2023 Universal Instruments Corporation.

All rights reserved. All specifications are subject to change.

AMERICAS

Tel. 1-800-432-2607

Tel. +1-607-779-7522

CHINA, SHENZHEN

Tel. +86-755-2685-9108

CHINA, SHANGHAI

Tel. +86-21-6495-2100

EUROPE

Tel. +421-2-4930-96-60

PENANG, MALAYSIA

Tel. +60-4-644-7067